	Туре	Hits	Search Text
1	BRS	20666	(fuse fusible) and loop\$3
2	BRS	745	S3 and "337"/\$.ccls.
3	BRS	355	S4 and parallel
4	BRS	390	S4 not S5
5	IS&R	2467	(337/36,159,171,176,177,229,231,290,29 1,293,295).CCLS.
6	BRS	20666	(fuse fusible) and loop\$3
7	BRS	189	S8 and S7
8	BRS	0	stitched adj fuse
9	BRS	153	stitched adj fus\$4
10	BRS	0	S10 and "337"/\$.ccls.
11	BRS	153	vortman.xa. and fuse

10/722,892

	T
	DBs
	US-PGPUB; USPAT;
1	USOCR; EPO; JPO;
	DERWENT; IBM TDB
	US-PGPUB; USPAT;
2	USOCR; EPO; JPO;
	DERWENT; IBM TDB
	US-PGPUB; USPAT;
3	USOCR; EPO; JPO;
	DERWENT; IBM_TDB
-	US-PGPUB; USPAT;
4	USOCR; EPO; JPO;
	DERWENT; IBM TDB
	US-PGPUB; USPAT;
5	USOCR; EPO; JPO;
	DERWENT; IBM TDB
	US-PGPUB; USPAT;
6	USOCR; EPO; JPO;
	DERWENT; IBM_TDB
	US-PGPUB; USPAT;
7	USOCR; EPO; JPO;
	DERWENT; IBM_TDB
	US-PGPUB; USPAT;
8	USOCR; EPO; JPO;
	DERWENT; IBM_TDB
	US-PGPUB; USPAT;
9	USOCR; EPO; JPO;
	DERWENT; IBM_TDB
	US-PGPUB; USPAT;
10	USOCR; EPO; JPO;
	DERWENT; IBM_TDB
	US-PGPUB; USPAT;
11	USOCR; EPO; JPO;
	DERWENT; IBM TDB

10/722,892